

~~SECRET~~

25X1A

☐ 3257-63  
Copy 6 of 6

13 September 63

MEMORANDUM FOR THE RECORD

SUBJECT : OXCART Status

1. OXCART Flights, 12 September:

- A. Aircraft #121 made flight #80, duration - 39 minutes, program - roughness investigation, max. Mach .9, max. altitude - 36,000 ft. Left engine afterburner surging and torching cancelled program. Investigating to determine cause of trouble.
- B. Aircraft #124 made flights #136 and #137, durations - 1:59 and 1:31 hours, programs - inflight refueling training. Several dry contacts and one wet 8000 lb. fuel transfer completed satisfactorily on each flight.

2. OXCART Status, 12 September:

- A. Aircraft #122: Engine ignition trouble on start. Cause of trouble determined to be a plugged chemical ignition probe. Procedure calls for periodic inspection and "as required" replacement of these probes.
- B. Aircraft #125: Engine afterburner failed to light at take-off position. Cause of trouble determined to be a plugged afterburner chemical ignition probe. Procedure calls for periodic inspection and "as required" replacement of these probes.
- C. Aircraft #126: Fin replacement.
- D. Aircraft #127: Waiting hardware for fin replacement.

~~SECRET~~

☐ Control System

25X1A

**SECRET**

Approved For Release 2002/09/03 : CIA-RDP63-00313A000500110046-5

25X1A

3257-63  
Page 2

- E. Aircraft #128: Final assembly, ninth week.
- F. Aircraft #129: Final assembly, second week.

SIGNED

25X1A

Aircraft Systems Division  
(Special Activities)

25X1A

:ASD/OSA:mvp (13 Sep 63)

**Distribution:**

- Cy 1 - AD/OSA
- 2 - D/TECH/OSA
- 354 - ASD/OSA
- 5 - ASD/OSA (chrono)
- 6 - RB/OSA

Approved For Release 2002/09/03 : CIA-RDP63-00313A000500110046-5

**SECRET**